

FW:
Fuller, Steve
to:
Richard Franklin
06/16/2011 10:02 AM
Cc:
"Martin, Bradley"
Show Details

Richard,

Just got off the phone with CCS. The coast guard made a mistake in their briefing. Some of the wire (see spread sheet) contains PCB (Black casing; red-black-yellow, yellow) other does not. CCS wanted to recycle it for copper content. Coast guard pushed back. CCS did not do an inventory of the wiring. Justin Piper (CCS) guessed that it should have been reported at 60 tons. But without an inventory it's just a guess. The ship weighs 2600 tons, so 60 tons would be 2% of the weight of the ship which does not seem out of line when you look at photos of the wire bundles.

I suggest we go with 60 tons. Let's say that ½ the weight is casing/shielding that will have to go as Haz waste for PCB content. The other half (copper wire) goes to recycling., if that is an overestimate no buddy gets hurt \$.

Please weigh in.

Best,
Steve

From: Wilson, Laura
Sent: Thursday, June 16, 2011 9:44 AM
To: Fuller, Steve
Subject:

Laura Wilson
Staff Consultant
Techlaw Inc.
101 Yesler Way, Suite 600
Seattle, WA 98104
206.577.3059 (O)
206.949.1395 (C)